


Odor Remediation Barrier - Details


5412 side Saddle Trail


Lighting:



Odor Remediation Project - Top Down View
5412 Side Saddle Trail


All additions
within Owners
property






NOTE: Post Holes sunk 24" cemented in Place

North Wall Fascia:



East Wall Framing:



NOTE: Post Holes sunk 24" cemented in Place

East Wall Fascia:

